

SAN JOSE JAPANTOWN HISTORIC CONTEXT AND RECONNAISSANCE SURVEY
San Jose, California

VOLUME I

September 20, 2004

Appendix G: Selected California Department of Parks and Recreation (DPR)
523A (Primary Record) forms

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: _____
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 2 Resource Name or #: (Assigned by recorder) San Jose Japantown Historic District

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5 & 6

c. Address _____ City _____ ZIP _____

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)
see attached District Record

*P3b. Resource Attributes: (List attributes and codes) not applicable

*P4. Resources Present: ☐ Building ☐ Structure ☐ Object ☐ Site ☒ District ☐ Element of District ☐ Other



P5b. Description of Photo:
view east of the intersection of East
Jackson and North 5th Streets. April

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

late 19th and 20th centuries, Santa
Clara County Assessor and Sanborn
Fire Insurance Company maps

*P7. Owner and Address

not applicable

*P8. Recorded By:

Carey and Co.
460 Bush Street
San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☐ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

*Resource Name or #: (Assigned by recorder) San Jose Japantown Historic District

D1. Historic Name

D2. Common Name

***D3. Detailed Description:** (Discuss overall coherence of the district, its setting, visual characteristics, and minor features. List all elements of the district.):

The San Jose Japantown Historic District has not been fully documented. This section of the District Record should be completed after the list of district contributors has been finalized. There are currently 67 potential contributors. See the attached report entitled "San Jose Japantown Historic Context & Reconnaissance Survey Project" (Carey & Co, 2004) for DPR 523A forms and more detailed information.

***D4 Boundary Description:** (Describe limits of district and attach map showing boundary and district elements.)

The San Jose Japantown Historic District is located in the City of San Jose's Japantown neighborhood. The district has not been fully documented, however the potential contributors are generally found along E Jackson Street between North 3rd and North 4th Streets and along North 5th and North 6th Streets between E Taylor and Empire Streets. See the attached report entitled "San Jose Japantown Historic Context & Reconnaissance Survey Project" (Carey & Co, 2004) for a map and more detailed information.

***D5 Boundary Justification:**

The potential boundaries of the San Jose Japantown Historic District were selected because they correspond to the historical and geographical focus of the Japanese American community in San Jose.

***D6 Significance: Theme:** Japanese American history

Area: City of San Jose

Period of Significance: 1890s-[undecided]

Applicable Criteria: NRHP Criterion A, potentially B & C

(Discuss district's importance in terms of its historical context as defined by theme, period of significance, and geographic scope. Also address integrity of the district as a whole.)

The San Jose Japantown Historic District has not been fully documented. This section of the District Record should be completed after the district contributors have been identified and the historic context statement has been updated to reflect any information discovered during the building-specific research phase. See the attached report entitled "San Jose Japantown Historic Context & Reconnaissance Survey Project" (Carey & Co, 2004) for the current historic context statement and recommendations on how to proceed with the building-specific research phase..

***D7 References:** (Give full citations including the names and addresses of any informants, where possible.)

See Appendix A in the attached report entitled "San Jose Japantown Historic Context & Reconnaissance Survey Project" (Carey & Co, 2004).

D8 Evaluator: Hisashi Sugaya and Sarah M. Dreller

Date: September 20, 2004

Affiliation and Address: Carey & Co., Inc., 460 Bush Street, San Francisco, CA, 94121

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 127 E Jackson ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; SE 1/4 of SE 1/4 of Sec 6

c. Address 127 E Jackson ST City San Jose ZIP 95112-5124

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24941050, Assessor's address: 605 N 4th ST

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This two-story commercial/retail building shares its parcel with two other buildings adjoined to the east and west. It is rectangular in plan with an asphalt shingle clad gable roof. The primary (south) façade faces Jackson Street and is clad in smooth stucco. The primary entry is denoted by a neon blade sign indicating the business name "Wings Chinese Restaurant" and an Asian-influenced surround consisting of engaged columns supporting a small hip roof with a Chinese ornamental motif. The glazed wood double entry doors are centered beneath the gable and flanked by an ocular window on either side and a fixed wood window to the west. Three double-hung vinyl windows are evenly spaced across the façade at the upper level. Other notable features exhibited on the primary façade include Asian-influenced ornamental elements such as a scalloped fascia, flared window surrounds, and a lantern at the gable peak. The rear (north) façade features several infilled window openings and is clad in narrow horizontal wood siding. The east and west façades are obscured by the adjacent buildings.

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:

South facade, looking north. April 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1940, Santa Clara County Assessor

*P7. Owner and Address

LOUIS KENG LU & CHOW SUSA &
2259 CASCADE ST

MILPITAS CA 95035-7805

*P8. Recorded By:

Carey and Co.
460 Bush Street
San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 131 E Jackson ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; SE 1/4 of SE 1/4 of Sec 6

c. Address 131 E Jackson ST City San Jose ZIP 95112-5124

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24941050, Assessor's address: 605 N 4th ST

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This two-story commercial/retail building shares its parcel with two other buildings adjoining to the east. It is rectangular in plan with an asphalt shingle clad gable roof. The primary (south) façade faces Jackson Street and is clad in narrow horizontal wood siding. The primary entry is denoted by a surface-mounted sign indicating the business name. The glazed wood double entry doors are centered beneath the gable with a transom and flanked by a large multi-lite fixed window on either side. Three double-hung vinyl windows are evenly spaced across the façade at the upper level. An early addition was made to the west façade with a shed roof and matching siding. The south façade of this addition features a roll-up metal garage door and a wood casement/combination window at the upper level. The west façade of the addition is residential in nature with wood fixed and casement windows and a secondary entry at the upper level and a fenced yard at the lower. Notable features exhibited on the primary façade include Asian-influenced ornamental elements such as a scalloped fascia, flared door and window surrounds, and a lantern at the gable peak. The rear (north) façade contains no openings or ornamentation and the east façade is obscured by the adjacent building.

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
South facade, looking northwest.
August 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1940, Santa Clara County Assessor

*P7. Owner and Address

LOUIS KENG LU & CHOW SUSA &
2259 CASCADE ST

MILPITAS CA 95035-7805

*P8. Recorded By:

Carey and Co.
460 Bush Street
San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 140 E JACKSON ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; SE 1/4 of SE 1/4 of Sec 6

c. Address 140 E JACKSON ST City San Jose ZIP 95112-5105

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24940061

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This single-story commercial/retail building is rectangular in plan with a flat roof. The primary (north) façade faces Jackson Street and is clad in wood board and batten; a shed parapet clad in faux barrel tile is also visible. At either end of the primary façade are large corner columns, and it is further characterized by a large fabric awning stretching the width of the building, located just below the shed parapet, that displays the name of the shop, "nichi bei bussan Martial Arts Kimonos Futons." The primary entry is located under this awning and is indicated by a recession containing glazed commercial doors. The entrance is flanked by fixed metal windows. The west façade is clad primarily in stucco and contains another entry, also recessed. Notable features include the shed parapet clad in faux barrel tile and the large corner columns.

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
North-west corner. April, 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1935/58, Santa Clara County
Assessor

*P7. Owner and Address

NICHI BEI BUSSAN INC

140 JACKSON ST

SAN JOSE CA 95112-5105

*P8. Recorded By:

Carey and Co.

460 Bush Street

San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 154 E JACKSON ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; SW 1/4 of SW 1/4 of Sec 5

c. Address 154 E JACKSON ST City San Jose ZIP 95112-5107

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24940030, Assessor's address: 184 E Jackson St

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This two-story commercial/retail building is rectangular in plan with a flat roof. It shares the same parcel with 162 and 168-170 Jackson Street. The primary (north) façade faces Jackson Street; it displays a fabric awning that extends across the width of the facade, visually dividing the first and second stories. The upper story is dominated by windows that are recessed under the projecting flat roof line. These windows are metal, one-lite fixed over metal sliders. The west facade of the upper story is clad in vertical metal siding. The lower story is clad in concrete block veneer. The primary entrance, located in the center of the north facade, is recessed and contains a glazed commercial door flanked by large fixed metal windows. "Omogari Korean Restaurant" is written on the fabric awning and painted on the west facade of the building. There is a parking lot to rear of the building, along the south facade.

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
Northwest facade. April, 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1965, Santa Clara County Assessor

*P7. Owner and Address

TODD R. & MASAMORI DEB FUJINA
158 JACKSON ST

SAN JOSE CA 95112-5107

*P8. Recorded By:

Carey and Co.
460 Bush Street
San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record
☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 162 E JACKSON ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; SW 1/4 of SW 1/4 of Sec 5

c. Address 162 E JACKSON ST City San Jose ZIP 95112-5107

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24940030, Assessor's address: 184 E Jackson St

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This two-story commercial building is rectangular in plan with a flat roof. It shares the same parcel with 154 and 168-170 E Jackson Street. The primary (north) facade faces Jackson Street and is clad in stucco; other facades are obscured by adjacent buildings. The upper story overhangs the lower story and is supported on projecting brackets. A rounded awning covers the main solid wood door located on the eastern half of the facade; this is the only entry on the front facade. A small one-lite window is situated at the first floor level towards the center of the facade. A sign reading "Bamboo" projects from the second story facade above the entrance, perpendicular to the building.

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
North facade, looking southeast. April 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1965, Santa Clara County Assessor

*P7. Owner and Address

TODD R. & MASAMORI DEB FUJINA
158 JACKSON ST
SAN JOSE CA 95112-5107

*P8. Recorded By:

Carey and Co.
460 Bush Street
San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record
☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 168 JACKSON ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; SW 1/4 of SW 1/4 of Sec 5

c. Address 168 JACKSON ST City San Jose ZIP 95112-5107

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN)

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24940030, Assessor's address: 184 E Jackson St

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This two-story commercial/retail building shares the same parcel with 162 E. Jackson Street and 154 E. Jackson Street; it is situated to the east of 162 E. Jackson and an exterior staircase giving access to the second floor of 168 E. Jackson is located between them. The building is rectangular in plan with a flat roof and stucco cladding. The primary (north) facade faces Jackson Street. A fabric awning extends across the width of this facade, visually dividing the first and second stories. Two entry doors are present on the primary facade, both of the glazed commercial type. Windows are metal fixed at both stories. Notable features include the horizontal incised stucco at the corners of the primary facade and applied wood posts separating the windows on the first and second floor levels.

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:

North facade, looking southeast. April, 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1965, Santa Clara County Assessor

*P7. Owner and Address

TODD R. & MASAMORI DEB FUJINA
158 JACKSON ST

SAN JOSE CA 95112-5107

*P8. Recorded By:

Carey and Co.
460 Bush Street
San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 169 E JACKSON ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 169 E JACKSON ST City San Jose ZIP 95112-5108

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24941071

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This two-story commercial/retail building is rectangular in plan with a flat roof. The primary (south) façade faces Jackson Street and is clad primarily in stucco with a random-coursed stone veneer base located under storefront windows; other facades are obscured by adjacent buildings. The façade is characterized by slightly projecting overhangs at the parapet and at the second floor plate, with the latter serving to visually divide the façade horizontally. The primary entry is indicated by a shallow recession over which hangs a sign for the shop; it contains glazed commercial doors. Two other secondary doors are present at either end of the primary façade. Windows are metal fixed and casement. Notable features include a slight projecting overhang at the parapet and pilasters at corners, as well as random-coursed stone veneer base under storefront windows.

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
South façade looking north-west.
April, 2004

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1955, Santa Clara County Assessor

*P7. Owner and Address

E & T PROPERTIES LLC

12312 JULIE LN

SARATOGA CA 95070-3042

*P8. Recorded By:

Carey and Co.

460 Bush Street

San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 175 E JACKSON ST

P1. Other Identifier: San Jose Tofu Company

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 175 E JACKSON ST City San Jose ZIP 95112-5108

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24941016

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This one-story commercial/retail building shares its parcel with 193 E. Jackson Street and occupies the west side of the lot. It is rectangular in plan with a flat roof. The primary (south) facade faces Jackson Street; adjacent buildings obscure the other facades. It is clad in stucco and displays a painted horizontal line design across the upper level of the facade; "San Jose Tofu Co." is painted at the center of the facade. The primary entry is recessed and denoted by a fabric awning that projects from the facade over the entranceway. The door is wood and the windows flanking the entrance are fixed vinyl.

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
South façade. August, 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1928, San Jose Historic Resources Inventory

*P7. Owner and Address

FREDERIC S. & LILLIE Y. MORITA
841 N 5TH ST

SAN JOSE CA 95112-5021

*P8. Recorded By:

Carey and Co.
460 Bush Street
San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 193 E JACKSON ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 193 E JACKSON ST City San Jose ZIP 95112-5108

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24941016, Assessor's address: 175 East Jackson Street

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This two-story commercial/retail building shares its parcel with 175 E. Jackson Street and occupies the east side of the lot. It is rectangular in plan with a flat roof and stucco cladding. The primary (south) facade faces Jackson Street and features a raised band at the parapet; the east facade is also visible and is adjacent to a parking area. The primary entry is located at the center of the primary facade; it is of the glazed commercial type and is recessed under a fabric awning reading "Gombei Restaurant" that projects from a metal header on the facade. The secondary entry is located on the east side of the facade and is arched. Windows at the first floor level on the primary facade are fixed metal; at the upper story on both the south and east elevations the windows are vinyl. Notable features include a sign projecting perpendicular to the primary facade above the center of the fabric awning.

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
South facade. April 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1928, Santa Clara County Assessor

*P7. Owner and Address

FREDERIC S. & LILLIE Y. MORITA
841 N 5TH ST

SAN JOSE CA 95112-5021

*P8. Recorded By:

Carey and Co.
460 Bush Street
San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 197 E JACKSON ST

P1. Other Identifier: Roy's Service Station

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 197 E JACKSON ST City San Jose ZIP 95112-5108

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN)

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24941015

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This single-story commercial/retail building is irregular in plan with a flat roof. It is of masonry construction, clad in stucco. The primary (south) façade faces Jackson Street and the building is located on the corner; it is divided visually into three sections. The primary entry (center section) is located at the southeast corner and is oriented toward the intersection; it is indicated by a slender columned porte cochere. The entry under this porte cochere consists of a wood and glass door and metal-framed corner windows. Garage openings with metal roll-up doors flank the entry. Notable features include Art-deco style stepping at the parapet, and curved edges at openings.

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
South façade looking north-east.
April, 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1939, Santa Clara County Assessor

*P7. Owner and Address

ROY S. & ESTHER S. MUROTSUNE

1616 HESTER AVE

SAN JOSE CA 95128-5220

*P8. Recorded By:

Carey and Co.

460 Bush Street

San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 198 E JACKSON ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 198 E JACKSON ST City San Jose ZIP 95112-5107

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24940001

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This single-story commercial/retail building is rectangular in plan with a flat roof. The primary (north) façade faces Jackson Street; a hipped parapet with exposed rafter tails and metal cladding in a faux tile style wraps around the northeast corner of the building. The building is clad in stucco with applied vertical timbers separating bays and it is further divided by the presence of fabric awnings on the north and east facades that indicate business entrances. The primary entry is located at the northeast corner and it is indicated by the overhanging parapet and a recession on the north façade; it contains glazed commercial doors at the north façade and fixed metal windows. This entry is further characterized by a wooden corner support column and two fabric awnings (one on each side) that display the name of the business, "Uchida Travel." Additional businesses are located along the north facade and one other is located on the east facade; their entrances contain wood and glass doors and windows are glazed commercial with metal sash, some fixed and some sliding. The west facade is plain and unmarked, clad in stucco.

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
North-east corner. April, 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1946, Santa Clara County Assessor

*P7. Owner and Address

NINOMIYA NURSERY CO

90 JACKSON ST

SAN JOSE CA 95112-5103

*P8. Recorded By:

Carey and Co.

460 Bush Street

San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 201 E JACKSON ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 201 E JACKSON ST City San Jose ZIP 95112-3202

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24939029

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This two-story commercial/retail building is rectangular in plan with a flat roof with a shallow overhang. It sits on a corner lot with the primary (south) façade facing Jackson Street. The primary entry is a recessed commercial storefront assembly denoted by a fabric awning with vertical wood slat cladding above. A secondary recessed entry is featured at the west end of the main façade. Several other tertiary entries are set into the east façade and called out with fabric awnings. The main body of the building is clad in stucco. Windows are fixed metal at the lower level and double-hung at the upper level. The Santa Clara County Assessor data, corroborated by Sanborn Fire Insurance Co. Maps, indicates that the building was constructed in 1900. It has been altered since that time; a comparison of Sanborn Maps demonstrates the presence of an early second-story wood balcony along the length of the south facade, wrapping around to the south portion of the west facade. This was removed by the 1950s. The roof was also changed from wood shingles to composition shingles by the 1950s. Visual observation indicates that the south and west facades have also been altered since 1900, including the second-story elaborations on the south facade and first story entryways.

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
South-west corner. April, 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1900, Santa Clara County Assessor/Sanborn Fire Insurance Co. Maps

*P7. Owner and Address

KO & KEIKO NAGAREDA

201 JACKSON ST

SAN JOSE CA 95112-3202

*P8. Recorded By:

Carey and Co.
460 Bush Street
San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 205 E JACKSON ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 205 E JACKSON ST City San Jose ZIP 95112-3202

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24939028, Assessor's address: 211 East Jackson Street

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This three-story commercial/retail building shares its parcel with 211 E. Jackson Street and occupies the west side of the lot. It is rectangular in plan with a truncated pyramidal roof clad in asphalt shingles. The primary (south) facade faces Jackson Street; adjacent buildings obscure the other facades. It is clad in stucco. The primary entry, located on the west half of the primary facade, is of the glazed commercial type and is recessed; a secondary entry is located on the east end of the facade. Windows at the lower story are metal fixed while at the upper story windows are double-hung wood. The upper portion of the second story windows and the openings at the storefront are all covered by vertical wood slat panels. Notable features also include horizontal bands incised on the lower half of the building and classical detailing at the cornice.

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
South façade looking north-
west. April, 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

c.1910, Sanborn Fire Insurance Co
Maps

*P7. Owner and Address

HENRY H. & MAE N. NISHIJIMA
209 JACKSON ST
SAN JOSE CA 95112-3202

*P8. Recorded By:

Carey and Co.
460 Bush Street
San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record
☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 208 E JACKSON ST

P1. Other Identifier: _____

***P2. Location:** ☐ Not for Publication ☒ Unrestricted

***a. County:** Santa Clara

***b. USGS Quad:** San Jose West **Date:** 1980 **T** 7S ; **R** 1E ; **NW** 1/4 of SW 1/4 of Sec 5

c. Address 208 E JACKSON ST **City** San Jose **ZIP** 95112-3201

d. UTM (Give more than one for large or linear resources **Zone** _____ **mE/** _____ **mN**

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24938029

***P3a. Description:** (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This single-story commercial/retail building is rectangular in form with a flat roof. It is located on the same parcel with and adjacent to 214 E Jackson Street. The primary (north) facade faces Jackson Street and is clad in stucco and brick veneer; the west facade is clad in the same materials. A fabric awning wraps around the northwest corner of the facade. The parapet is divided by vertical wood members into two rectangular sections on the north facade and three rectangular sections on the west facade. The primary entrance is located on the north facade and is indicated by a recession. It contains a glazed commercial entry flanked by fixed metal commercial windows that also continue under the awning around to the west facade. Notable features include a brick-clad center section of the exterior wall on the west facade.

***P3b. Resource Attributes:** (List attributes and codes) HP6. 1-3 story commercial building

***P4. Resources Present:** ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
Northwest facade, looking south.
April, 2004.

***P6. Date Constructed/Age Sources:**

☒ Historic ☐ Prehistoric ☐ Both

1953, Santa Clara County Assessor

***P7. Owner and Address**

EDITH C. HASHIMOTO

1140 N 3RD ST

SAN JOSE CA 95112-4958

***P8. Recorded By:**

Carey and Co.

460 Bush Street

San Francisco, CA 94108

***P9. Date Recorded:** 9/20/2004

***P10. Survey Type:**

Reconnaissance

***P11. Report Citation:** (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

***Attachments:** ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 211 E JACKSON ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 211 E JACKSON ST City San Jose ZIP 95112-3202

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24939028,

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This two-story commercial/retail building shares its parcel with 205 E. Jackson Street and occupies the east side of the lot. It is rectangular in plan with a flat roof. The primary (south) facade faces Jackson Street and displays a tile-clad shed parapet; adjacent buildings obscure the other facades. The building is clad in stucco and a fabric awning projects over the width of the facade at the first story. The primary entry, located on the west half of the primary facade, is of the glazed commercial type and is recessed. Windows at the lower story are metal fixed while at the upper story windows are metal sliders. Notable features also include horizontal bands incised on the lower half of the building and classical detailing at the cornice. Notable features include quoining at edges and false keystones over the second story windows.

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial company

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
South facade. August 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1940/45, Santa Clara County
Assessor

*P7. Owner and Address

HENRY H. & MAE N. NISHIJIMA

209 JACKSON ST

SAN JOSE CA 95112-3202

*P8. Recorded By:

Carey and Co.

460 Bush Street

San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 214 E JACKSON ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 214 E JACKSON ST City San Jose ZIP 95112-3201

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24938029, Assessor's address: 214 East Jackson Street

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This single-story commercial/retail building is rectangular in form with a flat roof. It is located on the same parcel with 208 E Jackson Street. The primary (north) facade faces Jackson Street and the parapet is clad in stucco while the exterior wall is clad in stack bond brick veneer; other facades are obscured by adjacent buildings. Two fabric awnings are present on the facade indicating business entrances. The parapet is divided by vertical wood members into three rectangular sections; the business to the east occupies the eastern third of the facade and its awning is centered in this section, while the other two-thirds of the facade is occupied by another business which has an awning across its entire width. The business to the east has a glazed commercial entry flanked by fixed metal commercial windows, the other business has two entrances of the same type. Notable features include a projecting neon sign over the western portion of the building.

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
North facade. August, 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1953, Santa Clara County Assessor

*P7. Owner and Address

EDITH C. HASHIMOTO

1140 N 3RD ST

SAN JOSE CA 95112-4958

*P8. Recorded By:

Carey and Co.

460 Bush Street

San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 221 E JACKSON ST

P1. Other Identifier: Taketa Building

***P2. Location:** ☐ Not for Publication ☒ Unrestricted

***a. County:** Santa Clara

***b. USGS Quad:** San Jose West **Date:** 1980 **T** 7S ; **R** 1E ; **NW** 1/4 of SW 1/4 of Sec 5

c. Address 221 E JACKSON ST **City** San Jose **ZIP** 95112-3202

d. UTM (Give more than one for large or linear resources **Zone** _____ **mE/** _____ **mN**

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24939027

***P3a. Description:** (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This two-story commercial/retail building is rectangular in plan with a flat roof. The primary (south) facade faces Jackson Street and displays a projecting hipped parapet clad in red tile. The building is clad primarily in stucco. The primary entrance, located at the southeast corner, is recessed and denoted by a full height glazed entry wall and a side wall clad in stack bond roman brick. Three storefronts are located to the west of this entrance, each with glazed commercial doors and fixed metal commercial windows. The two to the east are indicated by fabric awnings, while the business at the west end is characterized by wood cladding and an asymmetrical gabled projection supported on wood brackets over its facade. Notable features include large neon lettering reading "Shanghai" affixed to the facade and another neon sign projecting at a right angle from the west side of the facade.

***P3b. Resource Attributes:** (List attributes and codes) HP6. 1-3 story commercial building

***P4. Resources Present:** ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
South façade looking north-west.
April, 2004.

***P6. Date Constructed/Age Sources:**

☒ Historic ☐ Prehistoric ☐ Both

1900/49, Santa Clara County
Assessor

***P7. Owner and Address**

DOBASHI PROPERTIES INC & HEN
240 JACKSON ST
SAN JOSE CA 95112-3201

***P8. Recorded By:**

Carey and Co.
460 Bush Street
San Francisco, CA 94108

***P9. Date Recorded:** 9/20/2004

***P10. Survey Type:**

Reconnaissance

***P11. Report Citation:** (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

***Attachments:** ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record
☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 224 E JACKSON ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 224 E JACKSON ST City San Jose ZIP 95112-3201

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24938030

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This two-story commercial building is rectangular in plan with a flat roof. The primary (north) facade faces Jackson Street; a shed parapet covered in faux red barrel style tile tops this view and the other facades are obscured by adjacent buildings. The lower half of the primary facade is clad in stucco that displays an incised block pattern, while the upper half is clad in brick. The primary entry is located in the center of the facade, it is slightly recessed and is of the glazed commercial type. A secondary door is located on the west end of the facade. The second story windows are arched with two fixed lights in the arch and horizontal sliding lites beneath. At the first floor level are large fixed metal windows flanking the main entry. These display a three-lite horizontal band over a large picture window. Above these windows is a solid transom that is repeated at the primary entranceway. Notable features include a neon blade sign projecting from above the primary entry.

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
North façade looking south-west.
April, 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1939, Santa Clara County Assessor

*P7. Owner and Address

WESLEY & PERRY DOBASHI

2332 LOMA PARK DR

SAN JOSE CA 95124-1134

*P8. Recorded By:

Carey and Co.

460 Bush Street

San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 229 E JACKSON ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 229 E JACKSON ST City San Jose ZIP 95112-3202

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN)

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24939026

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This single-story commercial/retail building is rectangular in plan with a flat roof. The primary (south) facade faces Jackson Street; it displays a tall parapet and is clad primarily in stucco. The base of the facade is decorated with ceramic tile in a diaper pattern. Other facades are obscured by adjacent buildings. Four storefront entries are recessed into the facade, each indicated by vaulted concrete canopies that project over the doorways. These are arranged asymmetrically with two canopies adjacent to each other on the east half of the facade and two canopies separated from each other on the west half of the facade. Door and window assemblies are of the glazed commercial type, the windows are tall and fixed.

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
South façade looking north-west.
April, 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1947/63, Santa Clara County
Assessor

*P7. Owner and Address

WRIGHT & GRACE KAWAKAMI
1225 CAMEO DR
CAMPBELL CA 95008-3635

*P8. Recorded By:

Carey and Co.
460 Bush Street
San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 230 E JACKSON ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 230 E JACKSON ST City San Jose ZIP 95112-3201

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24938046

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This single-story commercial building is rectangular in plan with a flat roof. The primary (north) facade faces Jackson Street; the other facades are obscured by adjacent buildings. The lower half of the front facade is clad in stucco while the upper half is clad in horizontal wood siding. Projecting molding framing this top wood-clad section further divides the facade visually into two halves. The primary entry is centered on the facade and indicated by a recession; it consists of a glazed commercial door. Fixed multi-lite metal windows with wood surrounds flank the entryway, one on each side. Notable features include the recessed entry space which is clad in vertical wood siding and planters that project below the storefront windows. Signage includes the name of the restaurant painted onto the top half of the facade ("Hukilau San Jose") and a small sign hung perpendicular to the building just above the entrance. Alterations are thematic such as applied bamboo around the entry door.

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
North façade looking south-west.
April, 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1947, Santa Clara County Assessor

*P7. Owner and Address

KO & KEIKO NAGAREDA

267 PENNYHILL DR

SAN JOSE CA 95127-1864

*P8. Recorded By:

Carey and Co.

460 Bush Street

San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 231 E JACKSON ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 231 E JACKSON ST City San Jose ZIP 95112-3202

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24939041

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This two-story commercial/retail building is rectangular in plan with a flat roof. The primary (south) facade faces Jackson Street and is clad in stucco; other facades are obscured by adjacent buildings. The facade displays a stylized parapet with three stepped/pointed projections and decorative plaster detailing. The primary entry, located in the center of the facade, is indicated by a recession and contains glazed commercial doors. A secondary entry located at the east end of the facade appears to have been infilled. Windows are fixed metal at the first-story and at the second-story are wood double-hung with upper sashes composed of a large pane topped by a band of small square panes. Notable features include a neon sign projecting perpendicular to the facade just above the main entrance.

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
South façade looking north-west.
April, 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1900/c. 1930, Santa Clara County
Assessor/visual observation

*P7. Owner and Address

KOGURA JAMES & T 2003 TRUST
729 N 19TH ST
SAN JOSE CA 95112-3039

*P8. Recorded By:

Carey and Co.
460 Bush Street
San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record
☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 240 E JACKSON ST

P1. Other Identifier: _____

***P2. Location:** ☐ Not for Publication ☒ Unrestricted

***a. County:** Santa Clara

***b. USGS Quad:** San Jose West **Date:** 1980 **T** 7S ; **R** 1E ; **NW** 1/4 of SW 1/4 of Sec 5

c. Address 240 E JACKSON ST **City** San Jose **ZIP** 95112-3201

d. UTM (Give more than one for large or linear resources **Zone** _____ **mE/** _____ **mN**

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24938047

***P3a. Description:** (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This single-story commercial/retail building is rectangular in plan with a flat roof. The primary (north) façade faces Jackson Street and is clad in a metal paneling system; other facades are obscured by adjacent buildings. The primary entry, located at the northwest corner of the building, is indicated by a large shallow recession containing automatic glazed commercial doors with recessed lighting above. The recessed entry is further divided by a fabric awning that displays the name of the shop, "Dobashi." Windows are fixed and metal framed. The façade is arranged horizontally with bands of metal panels at the top and bottom separated by bands of windows in the middle; the windows occupy approximately half of the façade. Notable features include a vertical neon blade sign at the east end of the façade (possibly historical) that reads "Dobashi" and the gridded facade created by the panel system.

***P3b. Resource Attributes:** (List attributes and codes) HP6. 1-3 story commercial building

***P4. Resources Present:** ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
North façade. April, 2004.

***P6. Date Constructed/Age Sources:**

☒ Historic ☐ Prehistoric ☐ Both

1954/55, Santa Clara County Assessor

***P7. Owner and Address**

DOBASHI PROPERTIES INC

240 JACKSON ST

SAN JOSE CA 95112-3201

***P8. Recorded By:**

Carey and Co.

460 Bush Street

San Francisco, CA 94108

***P9. Date Recorded:** 9/20/2004

***P10. Survey Type:**

Reconnaissance

***P11. Report Citation:** (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

***Attachments:** ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 248 E JACKSON ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 248 E JACKSON ST City San Jose ZIP 95112-3201

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24938048, Assessor's address: 250 East Jackson Street

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This two-story commercial/retail building shares its parcel with 250 E. Jackson Street and occupies the west side of the lot. It is rectangular in plan with a gable roof clad in asphalt shingles. The primary (north) facade faces Jackson Street; adjacent buildings obscure the other facades. It is clad in stucco and is divided visually into two bays, the east wider than the west, separated by three deco-style vertical pilasters that rise above the roofline. The east bay displays a tile-clad shed parapet. The primary entry is in the center of the east bay facade and is of the glazed commercial type. This entry is covered by a fabric awning that stretches the entire width of the bay. The secondary entry at the west bay consists of a wood and glass door and a tiled base beneath its storefront window; it is also covered by a fabric awning. Windows at the first story are fixed metal while the upper story windows (on the east bay facade only) are metal sliders.

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
North facade. April, 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1959, Santa Clara County Assessor

*P7. Owner and Address

REISO & SUZUKO KAKE

2697 ORINDA DR

SAN JOSE CA 95121-1233

*P8. Recorded By:

Carey and Co.

460 Bush Street

San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 250 E JACKSON ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 250 E JACKSON ST City San Jose ZIP 95112-3201

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24938048

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This one-story commercial building shares its parcel with 248 E. Jackson Street and occupies the east side of the lot, located on the corner of Jackson and Sixth Street. It is rectangular in plan with a flat roof that overhangs the exterior walls and is clad in stucco with vertical timbers applied to the facades. The primary (north) facade faces Jackson Street and the secondary (east) facade faces Sixth Street; the other facades are obscured by adjacent buildings. The primary entry, located at the north facade, is recessed with a wood and glass door and covered by a projecting metal awning. A similar awning covers the windows and door on the east facade. Windows are metal sliders.

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
North facade. April 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1959, Santa Clara County Assessor

*P7. Owner and Address

REISO & SUZUKO KAKE

2697 ORINDA DR

SAN JOSE CA 95121-1233

*P8. Recorded By:

Carey and Co.

460 Bush Street

San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 600 N 3RD ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; SE 1/4 of SE 1/4 of Sec 6

c. Address 600 N 3RD ST City San Jose ZIP 95112-5119

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24941051

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This two-story residential building is currently used for offices. It is rectangular in plan and set on a corner lot with its primary façade (west) facing Third Street and a parking lot to the east. The dual-pitched, hipped roof and prominent cross gambrel is covered in asphalt shingles. At the building's north-west corner, an octagonal tower rises with a hipped roof. The building is clad at the base, below a molded watertable, in wide horizontal wood siding and above in narrow horizontal siding. The upper level and gambrel ends are clad in wood shingles. The primary entry is centered on the west façade within a recessed porch with stairways flanked by simple columns. The entry consists of a solid wood door surrounded by large fixed windows and transom. Some double-hung wood windows remain, mostly on the north façade, however most windows have been changed to metal fixed, double-hung, or sliders. Windows on the north façade are shaded by individual awnings. Other features include small shed dormers on the north and west sides of the roof, an arched window in the south gambrel end, and a bay projection below the gambrel on the south facade. A single-story shed roof addition to the east provides access from the parking lot. This entry is denoted by a large arched canopy.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property, HP6. 1-3 story commercial building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
South façade looking north-east.
April, 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1900/60, Santa Clara County
Assessor

*P7. Owner and Address

WAYNE M. & BETTY N. KANEMOTO
15994 CAMINO VISTA WAY
SAN JOSE CA 95127-2703

*P8. Recorded By:

Carey and Co.
460 Bush Street
San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record
☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 608 N 3RD ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; SE 1/4 of SE 1/4 of Sec 6

c. Address 608 N 3RD ST City San Jose ZIP 95112-5119

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24941052

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This one-story residential building is rectangular in plan with a hip roof clad in asphalt shingles. The house is clad in stucco and a stucco-clad exterior chimney is present on the south facade. The primary (west) facade faces Third Street and features a large projecting entry porch. This primary entry is characterized by shaped arched openings at the north, west, and south sides. The door is wood and windows are complex with wood fixed flanked by one-over-one wood double-hung. Notable details include wide overhanging eaves and the shaped elements associated with the entry porch.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
West facade looking northeast, April 2004

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1924, Santa Clara County Assessor

*P7. Owner and Address

STEPHEN G. & SANDRA M. WONG

608 N 3RD ST

SAN JOSE CA 95112-5119

*P8. Recorded By:

Carey and Co.

460 Bush Street

San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 588 N 4TH ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; SW 1/4 of SW 1/4 of Sec 5

c. Address 588 N 4TH ST City San Jose ZIP 95112-5311

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24940027-24940028

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This three-story community building occupies two parcels. It is rectangular in plan with a complex roof covered in faux barrel tile asphalt shingles; the building is clad in stucco. The primary (west) facade faces Fourth Street and is characterized by a front gable projection at the center of the facade. The upper stories overhang the first story at this facade, creating covered parking spaces. The primary entry is located at the center of the facade under the projecting front gable section. A cylindrical metal beam across the top of the opening displays a sign reading "588 N. Fourth St. Yu-Ai Kai." Doors are of the glazed commercial type and windows are metal fixed. Notable features include the complex roof plan, triangular louvered vents in the gable ends, and a concrete bench located near the sidewalk in front of the building that reads "Dedicated to the Issei Pioneers."

*P3b. Resource Attributes: (List attributes and codes) HP13. Community center/social hall

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
West facade looking southeast, April 2004

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1993, Santa Clara County Assessor

*P7. Owner and Address

JAPANESE AMER COMM SENIOR S
588 N 4TH ST

SAN JOSE CA 95112-5311

*P8. Recorded By:

Carey and Co.
460 Bush Street
San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 599 N 4TH ST

P1. Other Identifier: George's Service Center

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; SW 1/4 of SW 1/4 of Sec 5

c. Address 599 N 4TH ST City San Jose ZIP 95112-5310

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN)

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24940062

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

These two single-story commercial/retail buildings share the same parcel located on a corner. Both are rectangular in plan with flat roofs and smooth stucco cladding. The primary service building features a wood and glass main entry door centered on its east façade and flanked by fixed wood corner wrapping windows. A secondary entry is located on the south façade. Also notable are the slender columned porte cochere extending to the east and the horizontal banding around the upper edge of the building. The secondary garage building features two large service openings with metal roll-up doors and a six lite fixed wood window centered on the east façade. The south façade of this building is clad in horizontal wood siding and a small shed addition had been added to the east end of the façade.

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
North façade. April, 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

c.1940, Sanborn Fire Insurance
Company maps & San Jose City
Directories

*P7. Owner and Address

FRED T. & CANDICE K. KIDO

599 N 4TH ST

SAN JOSE CA 95112-5310

*P8. Recorded By:

Carey and Co.

460 Bush Street

San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 605 N 4TH ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; SE 1/4 of SE 1/4 of Sec 6

c. Address 605 N 4TH ST City San Jose ZIP 95112-5124

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24941050

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This two-story commercial/retail building shares its parcel with two other buildings adjoined to the west and occupies the corner of the lot. It is rectangular in plan with a flat parapet roof and stucco cladding. The primary (south) façade faces Jackson Street and the secondary (east) façade faces Fourth Street. The primary entry is angled at the south-east corner with a wood and glass door and emphasized by a concrete vertical fin featuring neon signage. The primary and secondary façades feature rows of large metal shop windows at the lower level and metal casement/fixed combination windows at the upper level, as well as secondary entries with wood and glass doors at the west and north ends of these façades. Other notable architectural details include incised horizontal lines at the parapet and between second-story windows, curved edges at openings, and a stucco clad cantilevering canopy above the lower-story windows that wraps the primary and secondary façades.

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
Southeast facade, looking northwest.
April, 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1940, Santa Clara County Assessor

*P7. Owner and Address

LOUIS KENG LU & CHOW SUSA &
2259 CASCADE ST
MILPITAS CA 95035-7805

*P8. Recorded By:

Carey and Co.
460 Bush Street
San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 609 N 4TH ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NE 1/4 of SE 1/4 of Sec 6

c. Address 609 N 4TH ST City San Jose ZIP 95112-5124

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24941049

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This one-story residential building with a commercial/retail use is rectangular in plan with a truncated pyramidal roof clad in asphalt shingles. Shed additions are present at the rear (west) of the house and the building is clad in horizontal wood siding. The primary (east) facade faces Fourth Street and displays a hip roof porch extending across the width of the facade, supported by classical style columns. The primary entry is at the center of the primary facade under the porch. The door is paneled wood with a transom above and windows are one-over-one wood double-hung. A sign reading "Kamimoto String Instruments" hangs from the center of porch. A storage shed is located on the lot to the west of the house.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property, HP6. 1-3 story commerical building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:

East facade, looking northwest. April 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1901, Santa Clara County Assessor

*P7. Owner and Address

GEORGE K. & SHIZUKA HANADA
722 N 19TH ST

SAN JOSE CA 95112-3038

*P8. Recorded By:

Carey and Co.
460 Bush Street
San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 610 N 4TH ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 610 N 4TH ST City San Jose ZIP 95112-5123

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24941070

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This two-story commercial/retail building is rectangular in plan with a flat-topped hip roof covered in asphalt shingles. The building is clad in stucco. It is located on a corner lot; the primary (south) facade faces Jackson Street and the secondary (west) facade faces Fourth Street. A number of businesses occupy the building and three doors are present on the primary facade while one is present on the secondary facade; each is indicated by a projecting bay overhead. The doors are wood paneled with transoms above. Windows are fixed metal. Notable features include blue tile decoration on the projecting bays, an elaborate bay at the west facade that displays a circular window, window and door surrounds of applied wood, and nine-lite opaque sections on both the upper part of the first story windows and on the lower part of the second story windows. At the north facade parking spaces are located under the second story, supported by beams, and surface parking occupies the remainder of the north portion of the lot.

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
Southwest corner. April, 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1984, Santa Clara County Assessor

*P7. Owner and Address

EDWIN W. COOK
777 N 1ST ST UNIT 5TH
SAN JOSE CA 95112-6337

*P8. Recorded By:

Carey and Co.
460 Bush Street
San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record
☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 623 N 4TH ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NE 1/4 of SE 1/4 of Sec 6

c. Address 623 N 4TH ST City San Jose ZIP 95112-5124

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24941046

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This one-story residential building is complex in plan with a cross gable roof clad in black asphalt tile. The house is clad in textured stucco. The primary (east) facade faces Fourth Street and is composed of a recessed primary entry on the south side and a front gable end on the north side. A projecting bay and an exterior chimney are visible on the south facade. The recessed entry is accessed via three pointed arch openings, one on the south facade and two on the primary facade. The roof over this recession is slightly flared. Windows are vinyl. A detached garage is also present on the site.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:

East facade, looking northwest. April 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1939, Santa Clara County Assessor

*P7. Owner and Address

ED & TSUKIYE MORIHIRO

623 N 4TH ST

SAN JOSE CA 95112-5124

*P8. Recorded By:

Carey and Co.

460 Bush Street

San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 624 N 4TH ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 624 N 4TH ST City San Jose ZIP 95112-5123

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24941023

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This 1.5-story residential building with basement and attic is rectangular in plan with a gable roof covered in asphalt shingles. The house is clad in stucco. The primary (west) facade faces Fourth Street and is composed of the gable end with a projecting front gable bay on the north half of the facade. The primary entry is a recessed entry porch with squared columns located to the south of the projecting gable bay. The door at the center of this facade under the porch is wood with diamond-shaped glass panels in the upper section. Windows are primarily one-over-one double-hung, with a fixed window at the projecting bay on the primary facade. Notable features include exposed rafter tails under the eaves and molded wood door and window surrounds.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
West facade, looking northeast. April 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1908, Santa Clara County Assessor

*P7. Owner and Address

SAN JOSE BUDDHIST CHURCH BE
640 N 5TH ST

SAN JOSE CA 95112-3234

*P8. Recorded By:

Carey and Co.
460 Bush Street
San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 646 N 4TH ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NE 1/4 of SE 1/4 of Sec 6

c. Address 646 N 4TH ST City San Jose ZIP 95112-5123

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)


APN # 24941026

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This one-story residential building is irregular in plan; the roof is hipped with a front gable to the west and a shed addition to the east, clad in asphalt shingles. The house is clad in horizontal wood siding. The primary (west) facade faces Fourth Street and is composed of the front gable end on the north side and a recessed entry porch with a lower hip roof covering on the south side. The primary entry is at this porch, accessed by stairs with a wood rail and supported by squared porch columns. The door is metal and windows are one-over-one wood double-hung. Wood trim surrounds the windows and door opening.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
West facade, looking east. April 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1901, Santa Clara County Assessor

*P7. Owner and Address

KENNETH Y. & TAE K. KAI

PO BOX 3136

SAN JOSE CA 95156-3136

*P8. Recorded By:

Carey and Co.

460 Bush Street

San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 510 N 5TH ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; SW 1/4 of SW 1/4 of Sec 5

c. Address 510 N 5TH ST City San Jose ZIP 95112-3232

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24938018

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This one-story commercial building is rectangular in plan with a gable roof clad in corrugated metal. The primary (west) facade faces Fifth Street; it is a false front with shaped parapet applied to the gable end, clad in stucco. The remainder of the building is clad in corrugated metal. The primary entry is recessed at the southwest corner and contains a wood door with diamond-pattern glass upper panel. Windows are one-over-one wood double-hung. Notable features include molded window surrounds, faux barrel tile along the ridge of the shaped parapet, and the curved painted name of the business ("National Printing Co.") that conforms to the shape of the parapet.

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
West facade, looking northeast. April 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1950/55, Santa Clara County Assessor

*P7. Owner and Address

DOUGLAS W. & BEVERLY WRIGHT

510 N 5TH ST

SAN JOSE CA 95112-3232

*P8. Recorded By:

Carey and Co.

460 Bush Street

San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 529 N 5TH ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; SW 1/4 of SW 1/4 of Sec 5

c. Address 529 N 5TH ST City San Jose ZIP 95112-3233

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24940010

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This two-story residential building is rectangular in plan with a front gable roof clad in asphalt shingles. A narrow one-story section projects off of the south facade. The primary (east) facade faces Fifth Street and features a projecting bay at the first story. The primary entry is located at the south end of the primary facade; it is a wood door with transom, covered by a bracket-supported projecting molding. Windows are two-over-two wood double-hung. Notable features include decorative brackets under the projecting roof; projecting molding with brackets over the door, windows, and bay; and wood panels under the windows of the projecting bay.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
East facade. April, 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1901, Santa Clara County Assessor

*P7. Owner and Address

IWAGAKI KENNETH J
15292 STRATFORD CT
MONTE SERENO CA 95030-2125

*P8. Recorded By:

Carey and Co.
460 Bush Street
San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record
☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 535 N 5TH ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; SW 1/4 of SW 1/4 of Sec 5

c. Address 535 N 5TH ST City San Jose ZIP 95112-3233

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24940009

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This one-story residential building with a community/museum use is irregular in plan with a hip roof clad in wood shingles. A large interior chimney is visible at the roof. The building is clad in stucco with brick veneer at the base. The primary (east) facade faces Fifth Street and contains a glazed commercial type addition at the north side. This rectangular addition functions as the primary entry with glazed commercial type door and windows. Windows at the stucco-clad portions of the building are multi-lite fixed. A freestanding sign with flared covering located on the front lawn identifies the building as a museum.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property, HP15. Educational building (museum)

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:

East facade, looking northwest. April 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1949, Santa Clara County Assessor

*P7. Owner and Address

AMERICAN RESOURCE CTR MUSE

535 N 5TH ST

SAN JOSE CA 95112-3233

*P8. Recorded By:

Carey and Co.

460 Bush Street

San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 545 N 5TH ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; SW 1/4 of SW 1/4 of Sec 5

c. Address 545 N 5TH ST City San Jose ZIP 95112-3233

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24940008

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This one-story residential building is square in plan with a pyramidal hip roof clad in tile. The house is clad in stucco. The primary (east) facade faces Fifth Street and displays a recessed entry at the south side. This entry is accessed through a shaped archway at the center of the facade. The door is wood and glass paneled and windows are complex with wood surrounds. Notable features include the shaped window-sized opening at the recessed entry porch; brick trim at the exterior chimney on the south facade; and the window configuration that appears to consist of a casement with a fixed panel overhead, flanked by double-hung.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
East facade, looking west. April 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1930, Santa Clara County Assessor

*P7. Owner and Address

HELEN & ALBERT K. MINETA

545 N 5TH ST

SAN JOSE CA 95112-3233

*P8. Recorded By:

Carey and Co.

460 Bush Street

San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 548 N 5TH ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; SW 1/4 of SW 1/4 of Sec 5

c. Address 548 N 5TH ST City San Jose ZIP 95112-3232

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24938023

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This one-story residential building is rectangular in plan with a gable roof clad in asphalt shingles. The primary (west) facade faces Fifth Street and is clad in stucco with brick veneer over lower portions. The front facing gable and lower gable entry porch feature large knee brackets supporting the overhanging roof. The gable entry porch is supported by brick columns and contains the primary entry, located on the south side of the facade. The door is wood with glass panels and sidelights; windows are one-over-one wood double-hung.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
West facade, looking northeast. April 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1919, Santa Clara County Assessor

*P7. Owner and Address

ERIC MORITA

*P8. Recorded By:

Carey and Co.
460 Bush Street
San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 565 N 5TH ST

P1. Other Identifier: Japanese Kuwabara Hospital

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; SW 1/4 of SW 1/4 of Sec 5

c. Address 565 N 5TH ST City San Jose ZIP 95112-3233

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24940007

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This 2.5-story community building, currently the "Issei Memorial Building," is rectangular in plan with a hip roof clad in asphalt shingles. The primary (east) facade faces Fifth Street and features a hipped dormer at the center of the roof with small gable projections on either end of the roof; a second story balcony is also present at the center of the facade, supported by the first floor porch posts. A turned wood railing surrounds the balcony and the porch posts are chamfered with simple molded capitals. The facade layout is symmetrical and it is clad in horizontal wood siding. The primary entry is located at the center of the east facade under the porch roof/second-story balcony. The double entry door is wood-framed with glass panel and displays a glass transom above. A similar double-door with transom is located at the center of the second story, giving access to the balcony. Windows are one-over-one wood double-hung.

*P3b. Resource Attributes: (List attributes and codes) HP13. Community center/social hall

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
East facade, looking northwest.
August 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1906, Santa Clara County Assessor

*P7. Owner and Address

AMERICAN CITIZENS LEAGUE SJ C
565 N 5TH ST

SAN JOSE CA 95112-3233

*P8. Recorded By:

Carey and Co.
460 Bush Street
San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 566 N 5TH ST

P1. Other Identifier: Wesley United Methodist Church

***P2. Location:** ☐ Not for Publication ☒ Unrestricted

***a. County:** Santa Clara

***b. USGS Quad:** San Jose West **Date:** 1980 **T** 7S ; **R** 1E ; **SW** 1/4 of SW 1/4 of Sec 5

c. Address 566 N 5TH ST **City** San Jose **ZIP** 95112-3232

d. UTM (Give more than one for large or linear resources **Zone** _____ **mE/** _____ **mN** _____)

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)


APN # 24938024, 24938025, and 24938026

***P3a. Description:** (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

Two religious buildings and a large surface parking lot, currently used by the Wesley United Methodist Church, occupy three parcels: 24938024, 24938025, and 24938026. The one-story church/sanctuary building is situated at the northwest corner of the site, while a two-story building is located along the eastern length of the site; both are clad primarily in stucco. The northwest building is complex in plan with an irregular roof clad in faux barrel tile. The primary (west) façade faces Fifth Street and the secondary (south) façade faces the parking lot. A recessed double doorway of the glazed commercial type indicates the primary entry on the west facade; a secondary entry is located on the south facade. The primary and secondary façades feature panels of vertical wood screens. The two-story eastern building is rectangular in plan with flat roof. Cantilevered beams project from the overhanging roof on the primary (west) facade. An exterior hallway at the second floor level is also supported by cantilevered beams and displays a metal railing. The building's rooms are accessed from the exterior, therefore numerous doors are visible on the west facade at both stories. Windows are wood fixed.

***P3b. Resource Attributes:** (List attributes and codes) HP16. Religious building

***P4. Resources Present:** ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:

Left: Northwest facade. Right:
Southwest facade. April 2004.

***P6. Date Constructed/Age Sources:**

☒ Historic ☐ Prehistoric ☐ Both

1913/51/64/74/89, church records &
Santa Clara County Assessor

***P7. Owner and Address**

UNITED METHODIST CHUCHOF SA
566 N 5TH ST

SAN JOSE CA 95112-3232

***P8. Recorded By:**

Carey and Co.
460 Bush Street
San Francisco, CA 94108

***P9. Date Recorded:** 9/20/2004

***P10. Survey Type:**

Reconnaissance

***P11. Report Citation:** (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

***Attachments:** ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 580 N 5TH ST

P1. Other Identifier: Old Dentist Office

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 580 N 5TH ST City San Jose ZIP 95112-3232

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24938039

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This one-story residential building is rectangular in plan with a gable roof clad in asphalt shingles. The building is clad in horizontal wood siding. The primary (west) facade faces Fifth Street and is the gable end; it is characterized by a triangular pediment entry porch supported on either front corner by a trio of Tuscan columns. The primary entrance under this porch is a paneled wood door with a row of lites in the upper panel. Windows at the west facade are stylized ten-over-one lite wood fixed; other windows are one-over-one wood double-hung. Notable features include the arched opening with a "keystone" at the entry porch (the porch is likely an addition), exposed rafter tails under the overhanging roof on the primary facade, decorative molding/trim around the door and windows at the primary facade, and a wood grid vent at the peak of the west gable end.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
West facade, looking east. April 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1900, Santa Clara County Assessor

*P7. Owner and Address

EDWARD T. & KIKUE & REALTOR M
2939 VIA CARMEN

SAN JOSE CA 95124-1445

*P8. Recorded By:

Carey and Co.
460 Bush Street
San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 592 N 5TH ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 592 N 5TH ST City San Jose ZIP 95112-3232

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN)

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24938040

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This one-story commercial building is irregular in plan with a flat roof. The primary (west) facade features a false front projection/addition at the south side of the facade with horizontal wood siding at the parapet and wood shingle cladding on the lower portion. The primary facade to the north of this section is clad in stucco, and the north facade of the building is clad in corrugated metal. The primary entry is located on the north face of the primary facade projection/addition. Windows on the stucco portion of the facade are wood fixed. A separate garage structure is located on the east side of the parcel.

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
West facade, looking southeast. April 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1900/56, Santa Clara County Assessor

*P7. Owner and Address

MARY R. GUERRA
590 N 5TH ST
SAN JOSE CA 95112-3232

*P8. Recorded By:

Carey and Co.
460 Bush Street
San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record
☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 607 N 5TH ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 607 N 5TH ST City San Jose ZIP 95112-3235

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24941014

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This two-story primarily residential building is rectangular in plan with a hipped roof covered in asphalt shingles and featuring exposed rafters. The primary façade (east) faces Fifth Street with commercial space at the lower level and residential at the upper level. The commercial portion of the primary façade consists of glazed commercial metal doors and fixed windows set into a base and corners of Roman brick veneer. The upper level of the primary façade is clad in vertical wood siding. A majority of the building's north, south, and west facades are stucco clad. The lower level projects slightly on the north facade allowing for a balcony with wood posts and rails above. Residential entries are located at the upper level off this balcony and windows are wood double-hung. Windows on the lower north, south, and upper east facades consist of an assembly of metal fixed flanked by metal casements. Asian-influenced manicured landscaping decorates the primary façade and sidewalk planter.

*P3b. Resource Attributes: (List attributes and codes) HP3. Multiple family property, HP6. 1-3 story commercial building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
North-east corner. April, 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1949, Santa Clara County Assessor

*P7. Owner and Address

ROY S. & ESTHER S. MUROTSUNE

1616 HESTER AVE

SAN JOSE CA 95128-5220

*P8. Recorded By:

Carey and Co.

460 Bush Street

San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 639 N 5TH ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 639 N 5TH ST City San Jose ZIP 95112-3235

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN)

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24941075

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This two-story community building is rectangular in plan with a flat-topped hip roof and overhanging eaves. The building is clad in stucco. It is located to the north of a large parking area; the primary (south) facade faces the parking lot and the secondary (east) facade faces Fifth Street. Second floor rooms are accessed via an exterior hallway at the south facade; rows of doors at the first and second floors are therefore visible at this facade. Windows are metal sliders. Notable features include a large applied circular decoration/sign at the second story on the east facade and the use of applied wood posts and beams to demarcate windows, doors and edges of the building facades.

*P3b. Resource Attributes: (List attributes and codes) HP13. Community center/social hall

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
Southeast facade, looking northwest.
April 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1950, Santa Clara County Assessor

*P7. Owner and Address

BUDDHIST CHURCH OF SAN JOSE
640 N 5TH ST

SAN JOSE CA 95112-3234

*P8. Recorded By:

Carey and Co.
460 Bush Street
San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 2 Resource Name or #: (Assigned by recorder) 640 N 5TH ST

P1. Other Identifier: S.J. Betsuin Buddhist Church

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 640 N 5TH ST City San Jose ZIP 95112-3234

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN)

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24939031

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This one-story religious building, currently used as a Buddhist temple, is L-shaped in plan with a tile roof. The main building is rectangular and a wing projects from the southeast facade to form an L- shape. It is situated on a large parcel containing one 2-story building to the north and one 2-story building to the south of the temple. An elaborately landscaped garden, located adjacent to the temple on the south, also characterizes the site.

The temple is covered in a steeply-pitched gable-on-hip roof with wide flared eaves. The primary (west) facade contains the main entry, indicated by a shed roof projection over stairs leading up to the building. Half-timbered gable ends are visible at the north and south elevations; these are decorated with carved and incised wood elements. Raised molded beams with ornamental end pieces highlight the ridge and the

(see continuation sheet)

*P3b. Resource Attributes: (List attributes and codes) HP16. Religious building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
Northwest facade, looking southeast.
April 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1937, church records

*P7. Owner and Address

BUDDHIST CHURCH OF S J

640 N 5TH ST

SAN JOSE CA 95112-3234

*P8. Recorded By:

Carey and Co.

460 Bush Street

San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☒ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

*Recorded by: Carey & Co.

*Date: 09/20/04

☒ Continuation

☐ Update

P3a. Description (con't):

outline of the roof form on the north and south sides. A row of raised circles making up a pattern on the decorated ridge beam is emphasized by matching circular end pieces affixed to the tile at the edges of the roof. Exposed rafter tails are visible under the eaves and both base and flying rafters are used. Supporting the eaves is a series of posts and beams that wrap around the building; the posts are topped by a bracket complex (*kumimono* or *tokyo*) that consists of a bearing block (*masu*) and a bracket arm (*hijiki*). The posts and beams supporting the projecting shed roof at the main entrance are further elaborated by carved decoration and chamfering on the beams, multi-tiered bracketing above the posts, and frog-leg style struts centered over the beams. A low wood railing borders the entrance stairs and encircles the porch around the building. Metal rails going up the stairs are also present alongside the posts that intersect with the wide front staircase. The entrance doors are tall wood-paneled with circular golden/metallic ornamentation in the upper panel. Windows are wood multi-lite horizontal sliding.

To the north of the temple is a two-story building, L-shaped in plan, with a complex tile roof. Like the temple, the tile ends are capped by decorative circular pieces. A shed roof covers the first story, with a gable-on-shed section at the west facade, and displays wide overhanging eaves. The second story is covered by an intersecting hip roof, also with wide eaves; the eastern half appears taller than the western half. The building is clad in stucco. The primary entry is located on the west facade at the rear (east end) of the building (the inner section of the "L") and contains a metal and glass door. Windows are primarily wood one-lite fixed at the first story and multi-lite fixed at the second.

The building to the south of the temple is complex in plan with a flat roof. It is composed of three attached rectangular sections: the tallest two-story south section forms the entire south portion of the building; a mid-sized two-story section with a north-facing primary facade is located the along the north side of the building; and a smaller two-story section with a west-facing primary facade is located at the northwest corner of the building. The primary entry for the building is at the northwest corner section on the west facade. The building is clad in stucco. The north facade of both the tallest two-story section and the mid-sized two-story section, and the west facade of the smaller northwest section, display large metal-sash windows recessed under projecting roof lines.

END.

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 645 N 5TH ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 645 N 5TH ST City San Jose ZIP 95112-3235

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24941009

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This one-story residential building is rectangular in plan with a pyramidal hip roof covered in asphalt shingles. A front gable projection facing Fifth Street composes the primary (east) facade and the building is clad in stucco. The primary entry is located in the center of the front gable end and consists of a small stoop with a gable roof awning over a screen door. Windows are large fixed at the primary facade and one-over-one wood double-hung at the north and south facades. A storage shed is present behind the house.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:

East facade, looking northwest. April 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1901, Santa Clara County Assessor

*P7. Owner and Address

SAN JOSE BUDDHIST CHURCH BE
640 N 5TH ST

SAN JOSE CA 95112-3234

*P8. Recorded By:

Carey and Co.
460 Bush Street
San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 649 N 5TH ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 649 N 5TH ST City San Jose ZIP 95112-3235

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24941008

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This one-story residential building is irregular in plan with a hip roof clad in asphalt shingles. The house is clad in stucco. The primary (east) facade faces Fifth Street and a hip wing projects toward the sidewalk on the north half of the facade. A projecting bay is present at the south end of the primary facade. The primary entry is located on the south facade of the hip wing projection and contains a wood door. Windows are wood multi-lite fixed and vinyl. A detached garage is also present on the site.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
Southeast facade, looking northwest.
April 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1946, Santa Clara County Assessor

*P7. Owner and Address

KELVIN D. & JODY KAMACHI

649 N 5TH ST

SAN JOSE CA 95112-3235

*P8. Recorded By:

Carey and Co.

460 Bush Street

San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 650 N 5TH ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 650 N 5TH ST City San Jose ZIP 95112-3234

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24939032

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This one-story residential building is irregular in plan with a hip roof clad in wood shingles. The house is clad in stucco. The primary (west) facade faces Fifth Street and features a projecting hip roof bay at the center and an exterior chimney. The primary entry is recessed to the south of the projecting bay and contains a wood panel door. Windows are fixed vinyl. A detached garage is also located at the site.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
West facade, looking southeast. April 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1948, Santa Clara County Assessor

*P7. Owner and Address

ALICE A. & TERRY Y. MARUYAMA

650 N 5TH ST

SAN JOSE CA 95112-3234

*P8. Recorded By:

Carey and Co.

460 Bush Street

San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 655 N 5TH ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 655 N 5TH ST City San Jose ZIP 95112-3235

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN)

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24941007

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This one-story residential building is irregular in plan with a cross-gable roof clad in wood shingles. Exposed rafter tails are visible under the eaves and an exterior chimney is located on the south facade. The house is clad in stucco. The primary (east) facade faces Fifth Street and a front gable wing projects toward the sidewalk on the north half of the facade. The primary entry is located in the corner next to this wing, flush with the south half of the east facade. A shallow quarter-round entry porch with a flat roof covers the door. Windows are vinyl. A detached garage is also present on the site.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
Southeast facade, looking northwest.
April 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1941, Santa Clara County Assessor

*P7. Owner and Address

LILY H. & AMY M. HAYASHIMOTO

655 N 5TH ST

SAN JOSE CA 95112-3235

*P8. Recorded By:

Carey and Co.

460 Bush Street

San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

Resource Name or #: (Assigned by recorder) 659 N 5TH ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NE 1/4 of SE 1/4 of Sec 6

c. Address 659 N 5TH ST City San Jose ZIP 95112-3235

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24941006

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This one-story residential building is irregular in plan with a hip roof clad in asphalt shingles. The house is clad in stucco. The primary (east) facade faces Fifth Street and a hip wing projects toward the sidewalk from the north half of this facade. The primary entry is located in the corner between this wing and the main east facade, oriented at a diagonal angle facing southeast, and covered by a round metal awning. The door is wood and windows are metal fixed. Notable features include horizontal grooves incised in the stucco creating bands.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
Southeast facade, looking northwest.
April 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1940, Santa Clara County Assessor

*P7. Owner and Address

HARRY S. & TOMIYE DOBASHI

659 N 5TH ST

SAN JOSE CA 95112-3235

*P8. Recorded By:

Carey and Co.

460 Bush Street

San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

Resource Name or #: (Assigned by recorder) 662 N 5TH ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 662 N 5TH ST City San Jose ZIP 95112-3234

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24939033

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This one-story residential building is L-shaped in plan with a flat roof and stucco cladding. The primary (west) facade faces 5th street and contains a recessed entry. A garage is prominent at the south side of this facade. The door is wood and windows are wood fixed.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:

West facade, looking southeast. April 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1950, Santa Clara County Assessor

*P7. Owner and Address

TOM H. & HISAKO OCHI

1601 PEACHWOOD DR

SAN JOSE CA 95132-2129

*P8. Recorded By:

Carey and Co.

460 Bush Street

San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 665 N 5TH ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NE 1/4 of SE 1/4 of Sec 6

c. Address 665 N 5TH ST City San Jose ZIP 95112-3235

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24941005

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This one-story residential building is rectangular in plan with a front gable roof clad in asphalt shingles. The house is clad in horizontal wood siding. The primary (east) facade faces Fifth Street and includes a lower projecting gable entry porch to the south side of the facade supported by squared columns. Both gable ends display large brackets supporting the overhanging roof. The primary entry is recessed under the gable porch and contains a wood door. Windows are complex with one-over-one wood double-hung flanking fixed. These tri-window sets on the primary facade are surrounded by wood trim.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:

East facade, looking southwest. April 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1916, Santa Clara County Assessor

*P7. Owner and Address

KINAGA TRUST

665 N 5TH ST

SAN JOSE CA 95112-3235

*P8. Recorded By:

Carey and Co.

460 Bush Street

San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 690 N 5TH ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 690 N 5TH ST City San Jose ZIP 95112-3207

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24939038

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This six-story apartment complex occupies the large parcel at the north end of the block, bounded by Fifth Street to the west, Taylor Street to the north, and Sixth Street to the east. It is rectangular in plan with a flat roof and stucco cladding. Driveway access to the complex is south of the building off of Fifth Street. The north and south facades are longer and display the apartment windows and balconies; east and west facades are shorter and contain fewer openings. Doors are of the glazed commercial type and windows are metal sliders. Notable features include projecting bays and balconies, and decorative elements such as projecting horizontal panels at the cornice and vertical ornamentation topped by fin-like projections at the east and west facades.

*P3b. Resource Attributes: (List attributes and codes) HP3. Multiple family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
Southwest facade, looking northeast.
April 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1976, Santa Clara County Assessor

*P7. Owner and Address

BUDDHIST CHURCH HOUSING SA
690 N 05TH ST

SAN JOSE CA 95112

*P8. Recorded By:

Carey and Co.
460 Bush Street
San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 517 N 6TH ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; SW 1/4 of SW 1/4 of Sec 5

c. Address 517 N 6TH ST City San Jose ZIP 95112-3238

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24938011

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This one-story residential building with basement is rectangular in plan and displays a hipped with cross gable roof clad in asphalt shingles. The house is clad in horizontal wood siding. The primary (east) facade faces Sixth Street and contains a shed roof entry porch at the northeast corner supported by turned columns. The front facing cross gable features decorative wood ornamentation and a shed window awning supported by brackets. The primary entry is accessed via wood rail stairs at the primary facade. Windows are vinyl with wood trim surrounds.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
East facade, looking northwest. April 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1901, Santa Clara County Assessor

*P7. Owner and Address

GLENDIA J. WADE

517 N 6TH ST

SAN JOSE CA 95112-3238

*P8. Recorded By:

Carey and Co.

460 Bush Street

San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

Resource Name or #: (Assigned by recorder) 529 N 6TH ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; SW 1/4 of SW 1/4 of Sec 5

c. Address 529 N 6TH ST City San Jose ZIP 95112-3238

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN)

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24938009

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This one-story residential building is rectangular in plan and displays a hipped with cross gable roof clad in asphalt shingles. The house is clad in horizontal wood siding. The primary (east) facade faces Sixth Street and contains a shed roof entry porch at the northeast corner supported by turned columns. The front-facing cross gable features decorative wood ornamentation. The primary entry is accessed via stairs at the northeast corner of the house or a wood rail ramp that covers the width of the primary facade. The door is wood and windows are one-over-one wood double-hung.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:

East facade, looking northwest. April 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1901, Santa Clara County Assessor

*P7. Owner and Address

ROBERT M. & ROSE A. OCHOA

529 N 6TH ST

SAN JOSE CA 95112-3238

*P8. Recorded By:

Carey and Co.

460 Bush Street

San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 565 N 6TH ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 565 N 6TH ST City San Jose ZIP 95112-3248

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN)

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24938007

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This two-story commercial/retail building is located south of and adjacent to 565A North Sixth Street, and north of a surface parking area, all on the same parcel. It is rectangular in plan with a flat roof; the lower story is clad in stucco and perforated metal screen panels cover the upper story. The primary (east) facade faces Sixth Street and contains the primary entry. A raised letter sign reading "Soko Ace Hardware" is located across the length of this facade, visually dividing the storefront and the upper story. The entry is of the glazed commercial type and large fixed metal windows line the east facade, wrapping around to the east portion of the south facade. Notable features include the large columns located at the north and south corners of the primary facade and the block lettering of the signage above the entry.

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
Southeast facade, looking northwest.
April 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1967, Santa Clara County Assessor

*P7. Owner and Address

ROBERT K. & SUMIYE ASHIZAWA

565 N 6TH ST

SAN JOSE CA 95112-3248

*P8. Recorded By:

Carey and Co.

460 Bush Street

San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 565 N 6TH ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 565 N 6TH ST City San Jose ZIP 95112-3248

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN)

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24938007, Address on building: 565A

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This two-story commercial building is located north of and adjacent to 565 North Sixth Street on the same parcel. It is rectangular in plan with a flat roof and projecting eaves. The primary (east) facade faces Sixth Street and is clad primarily in brick; the north facade is clad in stucco. A fabric awning at the north side of the primary facade denotes the primary entry. The door under this awning is of the glazed commercial type, while a secondary doorway at the south end of the facade is composed of wood slats in a fretwork pattern. A vertical wood slat screen covers the lower story window at the primary facade. The name of the restaurant that currently occupies the first story, "Okayama," is written on the fabric awning, as well as on a neon sign that projects perpendicular to the building on the primary facade, and on another sign affixed to the north facade.

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
Northeast facade, looking west.
August 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both
1967, Santa Clara County Assessor

*P7. Owner and Address

ROBERT K. & SUMIYE ASHIZAWA
565 N 6TH ST
SAN JOSE CA 95112-3248

*P8. Recorded By:

Carey and Co.
460 Bush Street
San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record
☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 587 N 6TH ST

P1. Other Identifier: Aikido

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 587 N 6TH ST City San Jose ZIP 95112-3238

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN)

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24938049

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This two-story community building is rectangular in plan with a gable roof clad in asphalt shingles. A one-story hipped addition projects from the south facade. The building is clad in horizontal wood siding. The primary (east) facade faces Sixth Street and is embellished by a false front applied to the gable end; a shed projection over the primary entry extends the width of the facade. The primary entrance is a set of wood double-doors located in the center of the east facade; another door is present under a shorter shed projection on the north facade. Windows are vinyl double hung and fixed. Notable features include a semi-circular louver in the upper portion of the false front and a large sign underneath it reading "Okida Hall."

*P3b. Resource Attributes: (List attributes and codes) HP13. Community center/social hall

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
Southeast facade, looking northwest.
April 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1940, Santa Clara County Assessor

*P7. Owner and Address

TADAO & GRACE KOGURA

14800 MCVAY CT

SAN JOSE CA 95127-2544

*P8. Recorded By:

Carey and Co.

460 Bush Street

San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 605 N 6TH ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 605 N 6TH ST City San Jose ZIP 95112-3240

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24939024

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This single-story commercial/retail building is rectangular in plan with a flat roof and a stepped parapet. It is located on a corner lot with its primary (south) façade facing Jackson Street. It is clad in stucco with both raised and applied geometric designs at the parapet of the primary façade. A single commercial entry is featured on the primary façade, while multiple entries to individual commercial spaces are set into the east façade. The north and west façades are obscured by adjacent buildings. The primary façade entry consists of a commercial glazed door located off-center and a large commercial metal window to either side. Five commercial entries are featured on the east façade consisting of commercial metal and glass doors with transoms, fixed metal windows, and wood frames.

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
South-east corner. April, 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

c.1899/1940, Santa Clara County Assessor

*P7. Owner and Address

KOGURA JAMES & T 2003 TRUST
729 N 19TH ST

SAN JOSE CA 95112-3039

*P8. Recorded By:

Carey and Co.
460 Bush Street
San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 621 N 6TH ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 621 N 6TH ST City San Jose ZIP 95112-3240

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24939040

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This two-story commercial/retail building is rectangular in plan with a gable roof concealed by a parapet. The primary (east) façade faces Sixth Street and is clad in stucco. The north, south, and west facades are obscured by surrounding buildings. The primary façade is divided vertically into three portions. The central portion is denoted by a recessed primary entry with a commercial glazed door, a corner display window, and two fixed ten-lite windows at the lower level and a block of four industrial metal hopper windows at the upper level. A blade sign is affixed to the building above the primary entry featuring the name of the central business. The flanking portions of the building are defined by secondary entries and single fixed windows at the lower level and single industrial windows at the upper level. The northern secondary entry provides access to the upper level, while the southern portion features a business identified by an awning over the entry and a flat sign at the upper south corner of the façade.

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:

East façade looking south-west. April, 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1954, Santa Clara County Assessor

*P7. Owner and Address

ALBERT T. & JANICE T. KOGURA

1129 CALCATERRA CT

SAN JOSE CA 95120-4114

*P8. Recorded By:

Carey and Co.

460 Bush Street

San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 625 N 6TH ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 625 N 6TH ST City San Jose ZIP 95112-3240

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24939022

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This two-story commercial building is rectangular in plan with a gable roof clad in asphalt shingles. The primary (east) facade faces Sixth Street and displays a false-front style parapet; a projecting balcony at the second floor level is covered by a metal-clad barrel vault roof. This balcony is bordered by a metal railing and turned columns support the barrel vault roof. The building is clad in horizontal wood siding with brick veneer present at the facade on the first floor. The primary entry is located at the north east corner and is denoted by a sign reading "Cuban Restaurant" that projects perpendicular to the facade from the balcony. This entry consists of wood double-doors containing small lites; two other secondary doorways are located at either end of the facade. A door is also present located in the center of the second floor balcony facade. Windows located at the first and second floor of the primary facade are wood double-hung with metal grille coverings.

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
Northeast facade, looking southwest.
April 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

c.1889/1920/50, Santa Clara County
Assessor

*P7. Owner and Address

CORPUS CHRISTOPHER & LINDIS
4217 WARBLER LOOP
FREMONT CA 94555-1155

*P8. Recorded By:

Carey and Co.
460 Bush Street
San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 627 N 6TH ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 627 N 6TH ST City San Jose ZIP 95112-3240

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24939042, Address on building: 635 N 6th

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This one-story community building is rectangular in plan with a gable roof clad in asphalt shingles. The primary (east) facade faces Sixth Street and is the gable end; the primary entry is located at the southeast corner and is recessed with wood doors. The roof at the south elevation overhangs the side patio and an intersecting gable section is visible at the southwest corner. A fabric awning across the primary facade, reading "Filipino Community Center," further denotes the primary entrance. The building is clad in stucco and windows are fixed metal-sash with metal grille covering at the primary facade. A brick wall with metal gates borders the outdoor area to the south of the community building. This area contains a one-story restroom facility to the south with a shed roof covered in asphalt shingles. It is rectangular in plan with stucco cladding.

*P3b. Resource Attributes: (List attributes and codes) HP13. Community center/social hall

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
Southeast facade, looking northwest.
April 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1960, Santa Clara County Assessor

*P7. Owner and Address

FILIPINO COMMUNITY OF S C CO I
2487 GLEN ELM WAY
SAN JOSE CA 95148-2565

*P8. Recorded By:

Carey and Co.
460 Bush Street
San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record
☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 651 N 6TH ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 651 N 6TH ST City San Jose ZIP 95112-3240

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24939016

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This two-story religious building is rectangular in plan with a flat roof and stucco cladding. The primary (east) facade faces Sixth Street and is distinguished by recessions forming a cross shape at each of three entries; the cross form at the center is elevated above the roof line and also projects from the facade. The primary entry is located under this projection in the center of the facade and consists of two wooden doors. There are also two secondary entrances, one at either end of the facade at the other two cross forms. Windows at the primary facade are wood with stained-glass lites. Other facades display vinyl windows. Notable features also include a neon sign reading "Prayer Garden" situated on the roof above the elevated center section of the facade.

*P3b. Resource Attributes: (List attributes and codes) HP16. Religious building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
Northeast facade, looking southwest.
April 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

c.1960, visual observation

*P7. Owner and Address

GARDEN PRAYER CHURCH OF GO
651 N 6TH ST

SAN JOSE CA 95112-3240

*P8. Recorded By:

Carey and Co.
460 Bush Street
San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

Resource Name or #: (Assigned by recorder) 655 N 6TH ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 655 N 6TH ST City San Jose ZIP 95112-3240

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24939015

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This one-story commercial building is rectangular in plan with a flat roof. The primary (east) facade faces Sixth Street and displays a slightly projecting roof overhang; the primary entry is located near the center of the facade and is denoted by an arched projecting fabric awning. The building is clad in stucco. The entrance consists of wood double doors with one-lite glass panel over wood panel. One window is visible at the primary facade to the south of the doorway; it is vinyl flanked by shutters with a semi-circular pediment above and projecting molding below. Notable features include faux quoining at the projecting north and south walls on the primary facade and a metal gate-like ornamentation on the roof. A sign reading "Aikido of Japantown" is affixed to the primary facade north of the entrance.

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
East facade, looking west. April 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1953, Santa Clara County Assessor

*P7. Owner and Address

GARDEN PRAYER CHURCH OF GO
651 N 6TH ST

SAN JOSE CA 95112-3240

*P8. Recorded By:

Carey and Co.
460 Bush Street
San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 657 N 6TH ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 657 N 6TH ST City San Jose ZIP 95112-3240

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24939014

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This one-story commercial building is rectangular in plan with a flat roof; a hip roof section is present at the rear of the building. The building is clad in stucco with horizontal wood siding on portions of the front facade. The primary (east) facade faces Sixth Street; it is characterized by a recessed primary entry. The door is wood with glass panel and a transom above. Windows are boarded over. Notable features include a faded commercial sign at the west end of the north facade.

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
Northeast facade, looking southwest.
April 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

1949, Santa Clara County Assessor

*P7. Owner and Address

GEORGE H. & TAMOTSU NISHIOKA
1629 W HEDDING ST

SAN JOSE CA 95126-1540

*P8. Recorded By:

Carey and Co.
460 Bush Street
San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary _____
HRI# _____
Trinomial _____
NRHP Status Code: N/A
Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 Resource Name or #: (Assigned by recorder) 665 N 6TH ST

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Santa Clara

*b. USGS Quad: San Jose West Date: 1980 T 7S ; R 1E ; NW 1/4 of SW 1/4 of Sec 5

c. Address 665 N 6TH ST City San Jose ZIP 95112-3240

d. UTM (Give more than one for large or linear resources Zone _____ mE/ _____ mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc. as appropriate)

APN # 24939012

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This two-story commercial building is rectangular in plan with a flat roof. The building is clad in brick. The primary (east) facade faces Sixth Street and displays a shaped parapet with inset blue tile decoration; evidence of past signage affixed to the facade is also visible above the storefront. The primary entrance is located in the center of the east facade, a doorway flanked by fixed windows; all of these openings appear to be boarded up at present. Windows at the second story of the primary facade are one-over-one wood double-hung, around the sides they are metal industrial type. Notable features include the brick bearing walls, decorative brickwork at the parapet, and the tile base at the main entry.

*P3b. Resource Attributes: (List attributes and codes) HP6. 1-3 story commercial building

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☒ Element of District ☐ Other



P5b. Description of Photo:
Northeast facade, looking southwest.
April 2004.

*P6. Date Constructed/Age Sources:

☒ Historic ☐ Prehistoric ☐ Both

c.1920, Santa Clara County
Assessor/Sanborn Fire Insurance Co.
maps

*P7. Owner and Address

GEORGE H. & TAMOTSU NISHIOKA
1629 W HEDDING ST
SAN JOSE CA 95126-1540

*P8. Recorded By:

Carey and Co.
460 Bush Street
San Francisco, CA 94108

*P9. Date Recorded: 9/20/2004

*P10. Survey Type:

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none")

San Jose Japantown Historic Context and Reconnaissance Survey, Carey & Co., September 2004

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record
☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photograph Record ☐ Other (list): _____